## MARINE POLLUTION SURVEILLANCE REPORT





Analysis Provided by: The National Oceanic and Atmospheric Administration/National Environmental Satellite, Data and Information Service (NOAA/NESDIS)

REPORT DATE: JUNE 19, 2011 REPORT TIME: 2015Z (1515 CDT)

ANALYST: KIBLER

DATA SOURCE: MODIST TERRA

MODE: MULTI-SPECTRAL RESOLUTION: 250 METERS

IMAGE DATE/TIME: 6/19/2011 1648Z (1148 CDT)

## Legend



Possible Oil

False-Positives (not oil)



Destroyed Taylor Platform: [ 28°56'9" N / 88°58'12" W ]

REMARKS: Oil slicks seen stretching east-northeast from Destroyed Taylor Platform. Oil slick is thirty-two miles long and averaging about 1 mile wide. There are two separate oil slicks due to cloud cover blocking the view and the connection of the two slicks. Latest wind data indicates oil slicks should continue to move toward the east-northeast.

