89°10'W

89°0'W

## **EXPERIMENTAL MARINE POLLUTION SURVEILLANCE** REPORT





29°10'N

29°0'N

Analysis Provided by: The National Oceanic and Atmospheric Administration/National Environmental Satellite, Data and Information Service (NOAA/NESDIS)


REPORT DATE: December 23, 2010 REPORT TIME: 2010Z (1410 CST) ANALYST: Myrga

DATA SOURCE: MODIS TERRA MODE: MULTI-SPECTRAL **RESOLUTION: 250 METER** IMAGE DATE/TIME: 12/23/2010 1701Z (1101 CST)



**REMARKS**:

A small oil slick was viewed in the vicinity of the destroyed Taylor Platform, the assumed point source. The possible oil slick is between 3-4 kilometers in length.



This is an experimental product of the Satellite Analysis Branch and not operationally maintained. We will do our best to make it available in a timely manner.