MARINE POLLUTION SURVEILLANCE REPORT





Analysis Provided by: The National Oceanic and Atmospheric Administration/National Environmental Satellite, Data and Information Service (NOAA/NESDIS)

REPORT DATE: MAY 22, 2012 REPORT TIME: 1847Z (1347 CDT)

ANALYST: TURK

DATA SOURCE: TERRA MODIS

MODE: Multispectral RESOLUTION: 250 meter

IMAGE DATE/TIME: 5/22/2012 1640Z (1140 CDT)

Legend



Possible Oil

False-Positives (not oil)



Destroyed Taylor Platform: [28°56'9" N / 88°58'12" W]

REMARKS:

A possible slick extended 6.6 miles to the south-southeast from the destroyed Taylor platform.

