MARINE POLLUTION SURVEILLANCE REPORT





Analysis Provided by: The National Oceanic and Atmospheric Administration/National Environmental Satellite, Data and Information Service (NOAA/NESDIS)

REPORT DATE: APRIL 11, 2012 REPORT TIME: 2045Z (1545 CDT) ANALYST: TURK/RAMIREZ

DATA SOURCE: MODIS TERRA

MODE: MULTISPECTRAL RESOLUTION: 250 METER

IMAGE DATE/TIME: 4/11/2012 1645Z (4/11/12 1145 CDT)

Legend



Possible Oil

False-Positives (not oil)



Destroyed Taylor Platform: [28°56'9" N / 88°58'12" W]

REMARKS:

A possible oil slick was detected approximately 20.5 miles to the southeast of the Birds Foot. The slick extended 5.8 miles to the southwest of the point source before curving another 6.2 miles to the east southeast of there. The area was under clear skies at the time with light winds from the north at 5 knots.

